


## **Mt Hood Rally** **Odometer Calibration**

There is not an opportunity prior to the first stage to calibrate your odometer. Use the following instruction to calibrate your odometer if you wish. The following signs occur at the indicated mileage.

- 0.00 Start at exit 64 from Interstate 84. Zero your odometer at the stop sign as indicated below. Follow Highway 35 South.



- 0.314 "Stop"
- 1.758 "Leaving National Scenic Area"
- 2.142 "Mile 100"
- 3.151 "Mile 99"
- 4.157 "Mile 98"
- 5.068 "Mile 97"
- 5.396 "Fir Mountain Rd" (Sign on left)
- 5.958 "Mile 96"
- 6.941 "Mile 95"
- 7.695 "Mile 94"
- 8.698 "Mile 93"
- 9.709 "Mile 92"
- 10.427 "Pine Mont Dr" (Sign on left)
- 10.708 "Mile 91"
- 11.358 "Gilhouley Rd"
- 11.733 "Mile 90"